

ANSI/IPC-D-310C

ORIGINAL PUBLICATION SEPTEMBER 1969
REVISION A PUBLISHED DECEMBER 1977
REVISION B DECEMBER 1985
REVISION C JUNE 1991

IPC STANDARD 1991

Guidelines for Phototool Generation and Measurement Techniques

APPROVED DECEMBER 20, 1990, AS AN

**AMERICAN NATIONAL
STANDARD**

AMERICAN NATIONAL STANDARDS INSTITUTE



A standard developed by the Institute for Interconnecting and Packaging Electronic Circuits

7380 N. Lincoln Avenue • Lincolnwood, IL 60646-1705 • (708) 677-2850 • Fax (708) 677-9570 • Telex 214814 IPC UR

Table of Contents

1.0 Introduction	1	5.4.3	Land Areas	22
1.1 Scope and Purpose	1	5.4.4	Isolated Conductor Areas (Plating Thieving)	22
1.2 General Considerations	1	5.4.5	Edge-tab Plating Areas	23
1.2.1 Artwork Identification	1	5.4.6	Board Outlines	23
1.3 Classifications	1	5.4.6.1	Manual Artwork Configuration	23
1.4 Dimensions And Tolerances	1	5.4.6.2	Automated Artwork Configuration	23
2.0 Documentation	1	5.5	Solder Mask Artwork	23
2.1 Applicable Documents	1	5.6	Quality Conformance Test Circuits	25
2.1.1 IPC	2	5.6.1	Quality Conformance Evaluations	25
2.1.2 American Astronomical Society (AAS) Photo Bulletin, 1973, No. 1	2	5.6.2	Recommended Location of Coupon Circuitry	25
2.1.3 ANSI Publications	2	5.6.3	Coupon Identification	25
2.1.4 Military Standards	2	5.6.4	Coupon Quantity and Location	25
2.2 Reference Documents	2	5.6.5	General Coupon Requirements	25
2.2.1 IPC	2	5.6.5.1	Tolerances	25
3.0 Terms & Definitions	2	5.6.5.2	Lands and Holes	25
4.0 General Manufacturing Considerations	11	5.6.5.3	Conductors	25
4.1 Manufacturing Considerations	11	5.6.5.4	Etched Letters	25
4.1.1 Etch-resist Considerations	15	5.6.5.5	Number and Type of Layers	25
4.1.2 Etchant Considerations	15	5.6.5.6	Interlayer Connection Holes	25
4.1.3 Conductor Profile Consideration	15	5.6.5.7	Constraining Cores	25
4.1.4 Metallic Resist	15	5.6.6	Process Control Test Coupons	26
4.1.5 Nonmetallic Resist	15	5.6.7	Individual Coupon Design	27
4.2 Plating Considerations	15	5.6.7.1	Coupon A	27
4.2.1 Pattern Plating	15	5.6.7.2	Coupon S	28
4.2.2 Panel Plating	16	5.6.8	Coupon B	28
4.3 Conductor to Process Relationships	16	5.6.9	Coupon C	28
4.4 Solder Mask Artwork	16	5.6.9.1	Coupon M	28
4.4.1 Design Constraints	16	5.6.9.2	Coupon N	28
4.4.2 Artwork Requirements	16	5.6.9.3	Coupon P	29
5.0 General Design Considerations	18	5.6.10	Coupon D	29
5.1 Modular Grid System	19	5.6.10.1	Option 1	29
5.2 Tooling Requirements	19	5.6.10.2	Option 2	30
5.2.1 Internal Indexing	19	5.6.11	Coupon E	31
5.2.2 External Indexing Targets	20	5.6.12	Registration Coupons	31
5.3 Artwork Elements and Views	20	5.6.12.1	Coupon F, Option 1	33
5.3.1 Artwork Identification	20	5.6.12.2	Coupon F, Option 2	33
5.3.2 Printed Wiring Board Legend	20	5.6.12.3	Coupon R	33
5.3.3 Board Identification Nomenclature	20	5.6.13	Coupon G	33
5.3.4 Component Symbolization	20	5.6.13.1	Coupon T	34
5.3.5 Legibility and Spacing Requirements	21	5.7	Artwork Conductor Width	34
5.3.6 Marking Artwork	21	5.8	Tolerance Guidelines	36
5.3.7 Drill Alignment Holes	21	5.8.1	Features Size Tolerances	36
5.4 Conductor Characteristics and Routing Techniques	21	5.8.2	Location Accuracy	37
5.4.1 Conductor Routing	21	5.8.3	Example, Using Tolerance Guidelines	38
5.4.2 Fillets	21			

6.0 General Imaging Selection Considerations	39	8.3.3	Multi-land Component Preforms	48
6.1 Introduction	39	8.3.4	Related Artwork Symbols	48
6.1.1 Registration	40	8.3.5	Precision-slit Artwork Tapes	48
6.2 Photo Resist	40	8.4	Techniques	49
6.2.1 Liquid Photo Resist	40	8.4.1	Registration Methods	49
6.2.2 Dry Film Resist	40	8.4.1.1	Artwork Markings	49
6.2.3 Screening	40	8.4.1.2	Pin Registration	49
6.2.4 Laser Direct Imaging	40	8.4.1.3	Land Master	50
7.0 Artwork Generation Process and Control	40	8.4.1.4	Registration with the Red and Blue Color Separation System	50
7.1 Artwork Generation Method Selection	40	8.4.2.2	Die Cut Preforms	52
7.2 Manual Artwork Generation	40	8.4.2.3	Precision-slit Tape	52
7.2.1 Drafting Aids	40	9.0 Cut-and-Strip Artwork	53	
7.2.2 Artwork Scale	40	9.1	Introduction	53
7.2.3 Drafting Error	40	9.2	Equipment	53
7.2.4 Limiting Tolerances on Finished Board	40	9.2.1	Cutting Tools	53
7.3 Input for Digitized (Semi-automatic) Data Generation	41	9.2.2	Table Surfaces	54
7.3.1 Input Data Required	41	9.2.3	Numerically Controlled	54
7.3.2 Material	41	9.3	Input	54
7.3.3 Technique and Equipment	42	9.4	Materials	54
7.3.4 Feature Positioning Considerations	43	9.5	Revisions	54
7.4 Input Data for Numerical Controlled Machines	43	10.0 Automated Vector Photoplotting Techniques ...	54	
7.4.1 Mechanized Production	43	10.1	Introduction	54
7.4.2 Phototooling Considerations	43	10.2	Vector Photo-plotting Equipment	54
7.5 Phototool Materials	44	10.2.1	Exposure Devices	54
7.5.1 Material Types	44	10.2.1.1	Photohead Operation	54
7.5.1.1 Silver Halide	45	10.2.1.2	Apertures	55
7.5.1.2 Molecular Dye Image Film	45	10.2.1.3	Lenses	55
7.6 Dimensional Stability	45	10.2.1.4	Plotting Surfaces	55
7.6.1 Thermal Expansion	45	10.2.1.5	Controllers	56
7.6.2 Humidity Effects	45	10.2.1.6	Dimensional Limitations	56
7.7 Densitometry	46	11.0 Automated Raster Plotting Techniques	57	
7.8 Equipment for Generating Artwork	46	11.1	Principal of Operation	57
7.8.1 Plotters	46	11.1.1	Laser Raster Plotting	57
7.8.2 Precision Camera	46	11.1.2	Adjacency Effects	57
7.8.3 Artwork Compensation Devices	46	11.1.3	Positives and Negatives	58
7.8.4 Vacuum Frame	47	11.2	Mechanical Operation	58
7.8.5 Film Processor	47	11.2.1	Laser Path	58
8.0 Tape and Preform Artwork	48	11.2.1.1	Write Beam	58
8.1 Introduction	48	11.2.1.2	Reference Beam	58
8.2 Aids, Tools and Equipment	48	11.2.1.3	Glass Imaging Capability	58
8.2.1 Light Tables	48	11.3	Data Interpretation	59
8.2.2 Knife Holders and Blades	48	11.4	Types of Laser Plotters	59
8.2.3 Precision Polyester & Plate Glass Grids	48	11.4.1	Drum Plotters	59
8.2.4 Artwork Carriers	48	11.4.2	Varying Pixel and Spot Sizes	59
8.3 Materials	48	11.4.3	Other Differences	60
8.3.1 Polyester Film	48	12.0 Direct Imaging	60	
8.3.2 Die-cut Tape Preforms	48	12.1	Principle of Operation	60
		12.2	Current Status	60

12.3	Direct Imaging Applications	60
12.4	Conclusion	61
13.0	Measurement Techniques and Quality Assurance	61
13.1	Introduction	61
13.2	Checking Techniques.....	61
13.3	Checking Standards.....	61
13.3.1	Manually Prepared Artwork	61
13.3.2	Artwork Master/Production Master	62
13.4	Measurement and Inspection Equipment...	62
13.4.1	Manual Devices	62
13.4.1.1	Low Power Magnification Devices.....	62
13.4.1.2	Microscope.....	63
13.4.2	Semi-automatic Devices	63
13.4.2.1	Densitometer	63
13.4.2.2	Optical Measuring Devices	63
13.4.3	Fully Automatic Devices.....	63
13.4.3.1	Machine Function.....	63
13.4.3.2	Defect Detection Logic.....	63
13.4.3.3	Image Acquisition.....	63
13.4.3.4	Image Processing	63
13.4.3.5	False Detection.....	64
13.5	Artwork Defects	64
13.5.1	Factors Affecting Film Tool Quality	64
13.5.2	Types of Inspection.....	64
13.5.3	Inspection Reports.....	64
13.5.4	Reject Criteria.....	64
13.5.5	Classification of Defects	64
13.5.5.1	Pinholes or Voids.....	64
13.5.5.2	Notches	65
13.5.5.3	Scratches.....	65
13.5.5.4	Opaque Spots or Flecks	65
13.5.5.5	Protuberance.....	65
13.5.5.6	Raggedness	66
13.5.5.7	Pattern Orientation.....	66
13.5.5.8	Pattern Registration.....	66
13.5.5.9	Density	66
13.5.5.10	Legibility	67
13.5.6	Enlarged Scale Tape Artwork	67
13.5.7	Photographic Film	68

Figures

Figure 3-1	Simplified flow chart of printed board design/fabrication sequence.....	3
Figure 3-2	Printed wiring viewing (ANSI/IPC-D-350)	4
Figure 3-3	Exploded view of printed wiring layer orientation vs. registered production master orientation with legend correct reading in copper on layers 1 and 4	5

Figure 3-4	A typical curve of density vs. log exposure (H and D curve); AB, toe; BC, straight-line portion; CF, shoulder; P, the inertia point; f, the fog density; D_{MAX} , maximum density $\tau = \tan \theta$	6
Figure 3-5	Example of mirrored pattern	7
Figure 3-6	The visible part of the frequency spectrum	8
Figure 3-7	Examples of panel drawings	9
Figure 4-1	Double sided process flow chart (typical).....	12
Figure 4-2	Multilayer rigid process flow chart (typical) ..	13
Figure 4-3	Multilayer flex process flow chart (typical)....	13
Figure 4-4	Multilayer rigid-flex process flow chart (typical)	14
Figure 4-5	Non-organic process flow chart (typical)	14
Figure 4-6	Etch factor in terms of outgrowth, undercut and overhang	15
Figure 4-7	Plating process diagram.....	17
Figure 4-8	Panel plating (liquid resist)	18
Figure 4-9	Pattern plating (liquid resist)	18
Figure 4-10	Panel plating (dry film resist).....	18
Figure 4-11	Pattern plating (dry film resist).....	18
Figure 5-1	External indexing targets and moire pattern locations	19
Figure 5-2	Artwork orientation	19
Figure 5-3	Moire pattern.....	20
Figure 5-4	Functional board marking	21
Figure 5-5	Coordinate board marking	21
Figure 5-6	Artwork layout considerations	22
Figure 5-7	Isolated conductor areas with non-functional lines	23
Figure 5-8	Drill alignment holes	24
Figure 5-9	Edge card connector (dimensions are for standardized use on PWB artwork)	24
Figure 5-10	Solder mask clearance	24
Figure 5-11	Location of test circuitry	26
Figure 5-12	Systematic path for implementation of SPC.	27
Figure 5-13	Test coupons A and B.....	27
Figure 5-14	Plated hole solderability coupon S.....	28
Figure 5-15	Test coupon C, external layers only	28
Figure 5-16	Coupon M, surface mounting solderability testing	29
Figure 5-17	Coupon N, surface mounting bond strength.	29
Figure 5-18	Coupon P, copper peel strength	30
Figure 5-19	Test coupon D, option 1, for process control of 4 layer boards.....	31
Figure 5-20	Example of a 10-layer coupon D, option 2 ...	32
Figure 5-21	Insulation resistance coupon E.....	34
Figure 5-22	Comb and "Y" pattern examples	34
Figure 5-23	Chip component cleanliness test pattern	35
Figure 5-24	Coupon F.....	35
Figure 5-25	Registration test coupon R	35
Figure 5-26	Solder resist adhesion test coupon G.....	36

Figure 5-27	Coupon T	36
Figure 5-28	Surface mount technology artwork	37
Figure 5-29	Photo plotter generated artwork.....	38
Table 5-5	Feature Location Accuracy Tolerance.....	38
Figure 7-1	Sample pencil printed wiring layout	41
Figure 7-2	Example of computer-aided artwork generation flow.....	42
Figure 7-3	Typical composition of phototools	44
Figure 7-4	Artwork camera.....	46
Figure 7-5	Camera copy board	46
Figure 7-6	Size change due to change in temperature..	47
Figure 7-7	Size change due to change in relative humidity	47
Figure 8-1	Artwork symbols	49
Figure 8-2	Basic all-purpose lands	50
Figure 8-3a	Typical targets used for datum points or indexing holes	51
Figure 8-3b	Universal target.....	51
Figure 8-3c	Registration targets	51
Figure 8-3d	Photographic reduction points	51
Figure 8-3e	Exposure indicators	51
Figure 8-4	Red and blue color separation system	51
Figure 8-5	"Necked down" conductors	52
Figure 10-1		55
Figure 10-2	Photoheads used on one type of numerical controlled plotter.....	55
Figure 10-3	Apertures prior to assembly in the holding fixture (wheel) shown in Figure 10-4	55
Figure 10-4	Typical aperture wheel	56
Figure 11-1	Vector plotting versus raster plotting	57
Figure 11-2	Adjacency effects - result of plotting a line with adjacent circles (similar to some fill routines on vector plotters)	57
Figure 11-3	Typical edge roughness of a raster plotter...	58
Figure 11-4	Edge roughness on a 10° line.....	58
Figure 11-5	Main components in a flatbed laser plotter..	59
Figure 13-1	Production and inspection steps for single image master	62
Figure 13-2	Production and inspection steps for photo-plotted master	62
Figure 13-3	Densitometer	63
Figure 13-4	Optical measuring device.....	63
Figure 13-5	Pinholes and voids.....	65
Figure 13-6	Notches.....	65
Figure 13-7	Scratches.....	65
Figure 13-8	Spots or flecks	65
Figure 13-9	Protuberance.....	66
Figure 13-10	Ragged edge	66
Figure 13-11	Misregistration.....	66
Figure 13-12	Ragged edges	67
Figure 13-13	Pinholes	67

Figure 13-14	Pinholes	67
Figure 13-15	Broken conductors	67
Figure 13-16	Scratch.....	68
Figure 13-17	Overexposure	68
Figure 13-18	Underexposure.....	68

Tables

Table 4-2		12
Table 4-3	Typical Values to be Added or Subtracted from the Desired Nominal Conductor Width in Order to Arrive at the Nominal Width on the Production Master	16
Table 5-1	Coupon Frequency Requirements	26
Table 5-2	Land and Hole Sizes for Qualification Boards .	33
Table 5-3	Conductor Width and Spacing for Coupon E .	34
Table 5-4	Feature Size Tolerances	37
Table 5-6	Example—Feature Size Tolerance Summation.	39
Table 5-7	Example—Location Accuracy Tolerance Summation.....	39
Table 7-1	Fundamental Phototool Implementation Processes	44
Table 7-2	Typical Material Dimensional Changes.....	44
Table 8-1	Precision-Slit Tape Size/Core Color Identification Chart.....	49