



IPC/WHMA-A-620E



Requirements and Acceptance for Cable and Wire Harness Assemblies

If a conflict occurs
between the English
language and translated
versions of this document,
the English version will
take precedence.

Developed by the IPC Task Group (7-31f) of the Product Assurance
Subcommittee (7-30) and WHMA

Supersedes:

IPC/WHMA-A-620D – January 2020
IPC/WHMA-A-620C – January 2017
IPC/WHMA-A-620B with
Amendment 1 – August 2013
IPC/WHMA-A-620B – October 2012
IPC/WHMA-A-620A – July 2006
IPC/WHMA-A-620 – January 2002

Users of this publication are encouraged to participate in the development
of future revisions.

Contact:

IPC
3000 Lakeside Drive, Suite 105 N
Bannockburn, Illinois
60015-1219
Tel 847 615.7100
Fax 847 615.7105

**Wiring Harness Manufacturers
Assoc.**
(An affiliate of IPC)
3000 Lakeside Drive, Suite 105 N
Bannockburn, Illinois
60015-1219
Tel 847 615.7100
email: contact.us@whma.org



IPC/WHMA-A-620F

Requirements and Acceptance for Cable and Wire Harness Assemblies

If a conflict occurs
between the English
language and translated
versions of this document,
the English version will
take precedence.

Developed by the IPC/WHMA-A-620 Task Group (7-31f) of the Product Assurance Committee (7-30) of Global Electronics Association

Global Electronics Association Standards and Artificial Intelligence (AI) Statement

Global Electronics Association is the trading name of IPC International, Inc., which owns the copyright to all IPC Standards and other IPC materials.

The Global Electronics Association explicitly prohibits:

- The integration or transfer of any data whether in the form of IPC books, standards, metadata, or other formats — into AI engines or algorithms by any person or entity, including authorized distributors and their end users.
- Activities involving data harvesting, text and data mining, enrichment, or the creation of derivative works based on this data, including the use of automated data collection methods or artificial intelligence.

Any breach of these provisions is considered a copyright infringement unless expressly authorized in advance in writing by the Global Electronics Association.

Supersedes:

IPC/WHMA-A-620E – October 2022
IPC/WHMA-A-620D – January 2020
IPC/WHMA-A-620C – January 2017
IPC/WHMA-A-620B with
Amendment 1 – August 2013
IPC/WHMA-A-620B – October 2012
IPC/WHMA-A-620A – July 2006
IPC/WHMA-A-620 – January 2002

Users of this publication are encouraged to participate in the development of future revisions.

Contact:

Global Electronics Association
3000 Lakeside Drive, Suite 105N
Bannockburn, Illinois
60015-1249
Tel 847 615.7100
Fax 847 615.7105

Table of Contents

1.0 General	1-1	1.13 Facilities	1-6
1.1 Scope	1-1	1.13.1 Field Assembly Operations	1-6
1.2 Purpose	1-1	1.13.2 Health and Safety	1-6
1.3 Classification	1-1	1.14 Electrostatic Discharge (ESD) Protection	1-6
1.4 Measurement Units and Applications	1-1	1.15 Tools and Equipment	1-6
1.4.1 Verification of Dimensions	1-1	1.15.1 Control	1-6
1.5 Definition of Requirements	1-1	1.15.2 Calibration	1-7
1.5.1 Inspection Conditions	1-2	1.16 Materials and Processes	1-7
1.5.1.1 Acceptable	1-2	1.17 Electrical Clearance	1-7
1.5.1.2 Defect	1-2	1.18 Contamination	1-7
1.5.1.2.1 Disposition	1-2	1.19 Rework/Repair	1-8
1.5.1.3 Process Indicator	1-2	1.19.1 Rework	1-8
1.5.1.4 Conditions Not Specified	1-2	1.19.2 Repair	1-8
1.5.1.5 Uncommon or Specialized Designs	1-2	1.19.3 Post Rework/Repair Cleaning	1-8
1.5.2 Material and Process Nonconformance	1-3	2.0 Applicable Documents	2-1
1.6 Process Control	1-3	2.1 IPC	2-1
1.6.1 Statistical Process Control	1-3	2.2 Joint Industry Standards	2-1
1.7 Order of Precedence	1-3	2.3 Society of Automotive Engineers (SAE)	2-1
1.7.1 Clause References	1-4	2.4 American National Standards Institute (ANSI)	2-1
1.7.2 Appendices	1-4	2.5 International Organization for Standardization (ISO)	2-2
1.8 Terms and Definitions	1-4	2.6 ESD Association (ESDA)	2-2
1.8.1 FOD (Foreign Object Debris)	1-4	2.7 United States Department of Defense (DoD)	2-2
1.8.2 Inspection	1-4	2.8 International Electrotechnical Commission (IEC)	2-2
1.8.3 Manufacturer (Assembler)	1-4	2.9 Aerospace Industries Association (AIA/NAS)	2-2
1.8.4 Objective Evidence	1-4	2.10 Electronics Industries Alliance	2-2
1.8.5 Process Control	1-4	2.11 ASTM International	2-2
1.8.6 Supplier	1-4	2.12 Institute of Electrical and Electronics Engineers	2-2
1.8.7 User	1-4	3.0 Wires	3-1
1.8.8 Diameter	1-4	3.1 Stripping	3-1
1.8.8.1 Conductor	1-4	3.2 Strand Damage and End Cuts	3-1
1.8.8.2 Wire	1-4	3.3 Conductor Deformation/Birdcaging	3-4
1.8.8.3 Strand	1-4	3.4 Twisting of Wires	3-6
1.8.9 Engineering Documentation	1-4	3.5 Insulation Damage – Stripping	3-7
1.9 Requirements Flowdown	1-4	4.0 Soldered Terminations	4-1
1.10 Personnel Proficiency	1-5	4.1 Materials and Components	4-1
1.11 Acceptance Requirements	1-5		
1.12 Inspection Methodology	1-5		
1.12.1 Process Verification Inspection	1-5		
1.12.2 Visual Inspection	1-5		
1.12.2.1 Lighting	1-5		
1.12.2.2 Magnification Aids	1-5		

Table of Contents

1.0	GENERAL	1-1	1.12.2	Visual Inspection	1-5
1.1	Scope	1-1	1.12.2.1	Lighting	1-5
1.2	Purpose	1-1	1.12.2.2	Magnification Aids	1-5
1.3	Classification	1-1	1.13	Facilities	1-6
1.4	Measurement Units and Applications	1-1	1.13.1	Field Assembly Operations	1-6
1.4.1	Verification of Dimensions	1-1	1.13.2	Health and Safety	1-6
1.4.2	Relationship of AWG and Wire Size	1-1	1.14	Electrostatic Discharge (ESD) Protection	1-6
1.5	Definition of Requirements	1-1	1.15	Tools and Equipment	1-6
1.5.1	Inspection Conditions	1-2	1.15.1	Control	1-6
1.5.1.1	Acceptable	1-2	1.15.2	Calibration	1-6
1.5.1.2	Defect	1-2	1.16	Materials and Processes	1-7
1.5.1.2.1	Disposition	1-2	1.17	Electrical Clearance	1-7
1.5.1.3	Process Indicator	1-2	1.18	Contamination	1-7
1.5.1.4	Conditions Not Specified	1-2	1.19	Rework/Repair	1-7
1.5.1.5	Uncommon or Specialized Designs	1-3	1.19.1	Rework	1-7
1.5.2	Material and Process Nonconformance	1-3	1.19.2	Repair	1-7
1.6	Process Control	1-3	1.19.3	Post Rework/Repair Cleaning	1-7
1.6.1	Statistical Process Control	1-3	2.0	APPLICABLE DOCUMENTS	2-1
1.7	Order of Precedence	1-4	2.1	IPC	2-1
1.7.1	Clause References	1-4	2.2	Joint Industry Standards	2-1
1.7.2	Appendices	1-4	2.3	Society of Automotive Engineers (SAE)	2-1
1.8	Terms and Definitions	1-4	2.4	International Organization for Standardization (ISO)	2-2
1.8.1	FOD (Foreign Object Debris)	1-4	2.5	ESD Association (ESDA)	2-2
1.8.2	Inspection	1-4	2.6	United States Department of Defense (DoD)	2-2
1.8.3	Manufacturer (Assembler)	1-4	2.7	International Electrotechnical Commission (IEC)	2-2
1.8.4	Objective Evidence	1-4	2.8	Aerospace Industries Association (AIA/NAS)	2-2
1.8.5	Process Control	1-4	2.9	Electronics Industries Alliance	2-2
1.8.6	Supplier	1-4	2.10	ASTM International	2-2
1.8.7	User	1-4	3.0	WIRES	3-1
1.8.8	Diameter	1-4	3.1	Stripping	3-1
1.8.8.1	Conductor Diameter	1-4	3.2	Strand Damage and End Cuts	3-1
1.8.8.2	Wire Diameter	1-4	3.3	Conductor Deformation/Birdcaging	3-3
1.8.8.3	Strand Diameter	1-4	3.4	Twisting of Wires	3-4
1.8.9	Engineering Documentation	1-4	3.5	Insulation Damage – Stripping	3-5
1.9	Requirements Flowdown	1-5	4.0	SOLDERED TERMINATIONS	4-1
1.10	Personnel Proficiency	1-5	4.1	Materials and Components	4-1
1.11	Acceptance Requirements	1-5	4.1.1	Materials	4-1
1.12	Inspection Methodology	1-5			
1.12.1	Process Verification Inspection	1-5			

Table of Contents (cont.)

4.1.1	Materials	4-1	4.8.5	Hook	4-37
4.1.1.1	Solder	4-1	4.8.5.1	Lead/Wire Placement	4-37
4.1.1.1.1	Solder Purity Maintenance	4-2	4.8.5.2	Solder	4-39
4.1.1.2	Flux	4-3	4.8.6	Cup	4-40
4.1.1.3	Adhesives	4-3	4.8.6.1	Lead/Wire Placement	4-40
4.1.1.4	Solderability	4-4	4.8.6.2	Solder	4-41
4.1.2	Gold Removal	4-4	4.8.7	Series Connected	4-43
4.2	Cleanliness	4-5	4.8.8	Connection Requirements – Lead/Wire Placement – AWG 30 and Smaller Diameter Wires	4-44
4.2.1	Presoldering	4-5	5.0	Crimp Terminations (Contacts and Lugs)	5-1
4.2.2	Postsoldering	4-5	5.1	Stamped and Formed – Open Barrel	5-3
4.2.2.1	Foreign Object Debris (FOD)	4-5	5.1.1	Insulation Support	5-4
4.2.2.2	Flux Residue	4-6	5.1.1.1	Inspection Window	5-4
4.2.2.2.1	Cleaning Required	4-6	5.1.1.2	Crimp	5-6
4.2.2.2.2	No-Clean Process	4-6	5.1.2	Insulation Clearance if No Support Crimp	5-8
4.3	Solder Connection	4-7	5.1.3	Conductor Crimp	5-9
4.3.1	General Requirements	4-9	5.1.4	Crimp Bellmouth	5-11
4.3.2	Soldering Anomalies	4-10	5.1.5	Conductor Brush	5-13
4.3.2.1	Exposed Basis Metal	4-10	5.1.6	Carrier Cutoff Tab	5-15
4.3.2.2	Partially Visible or Hidden Solder Connections	4-10	5.1.7	Individual Wire Seal	5-16
4.4	Wire/Lead Preparation, Tinning	4-11	5.2	Stamped and Formed – Closed Barrel	5-18
4.5	Wire Insulation	4-13	5.2.1	Insulation Clearance	5-19
4.5.1	Clearance	4-13	5.2.2	Insulation Support Crimp	5-20
4.5.2	Postsolder Damage	4-15	5.2.3	Conductor Crimp and Bellmouth	5-21
4.6	Insulation Sleeve	4-16	5.2.4	Cutoff Tabs	5-23
4.7	Soldered Strand Separation (Birdcaging)	4-18	5.3	Machined Contacts	5-24
4.8	Terminals	4-19	5.3.1	Insulation Clearance	5-24
4.8.1	Turrets and Straight Pins	4-22	5.3.2	Insulation Support Style	5-26
4.8.1.1	Lead/Wire Placement	4-22	5.3.3	Conductor	5-27
4.8.1.2	Solder	4-24	5.3.4	Crimping	5-29
4.8.2	Bifurcated	4-25	5.3.5	CMA Buildup	5-31
4.8.2.1	Lead/Wire Placement – Side Route	4-25	5.4	Termination Ferrule Crimp	5-33
4.8.2.2	Lead/Wire Placement – Bottom and Top Route	4-27	5.5	Shrink Sleeve – Wire Support – Crimped Terminals	5-35
4.8.2.3	Lead/Wire Placement – Staked/Constrained Wires	4-29	6.0	Insulation Displacement Connection (IDC)	6-1
4.8.2.4	Solder	4-30	6.1	Mass Termination, Flat Cable	6-2
4.8.3	Slotted	4-32	6.1.1	End Cutting	6-2
4.8.3.1	Lead/Wire Placement	4-32	6.1.2	Notching	6-3
4.8.3.2	Solder	4-33	6.1.3	Planar Ground Plane Removal	6-4
4.8.4	Pierced/Perforated/Punched	4-34	6.1.4	Connector Position	6-5
4.8.4.1	Lead/Wire Placement	4-34	6.1.5	Connector Skew and Lateral Position	6-8
4.8.4.2	Pierced/Perforated/Punched – Solder	4-36	6.1.6	Retention	6-9

Table of Contents (cont.)

4.1.1.1	Solder	4-1	4.8.5.1	Lead/Conductor(s) Placement	4-33
4.1.1.1.1	Solder Purity Maintenance	4-2	4.8.5.2	Solder	4-34
4.1.1.2	Flux	4-3	4.8.6	Cup	4-35
4.1.1.3	Adhesives	4-3	4.8.6.1	Lead/Conductor(s) Placement	4-35
4.1.1.4	Solderability	4-3	4.8.6.2	Solder	4-36
4.1.2	Gold Removal	4-3	4.8.7	Series Connected	4-38
4.2	Cleanliness	4-4	4.8.8	AWG 30 and Smaller Diameter Wires	4-39
4.2.1	Presoldering	4-4	5.0	CRIMP TERMINATIONS (CONTACTS AND LUGS)	5-1
4.2.2	Postsoldering	4-4	5.1	Stamped and Formed – Open Barrel	5-3
4.2.2.1	Foreign Object Debris (FOD)	4-4	5.1.1	Insulation Support	5-4
4.2.2.2	Flux Residue	4-5	5.1.1.1	Inspection Window	5-4
4.2.2.2.1	Cleaning Required	4-5	5.1.1.2	Crimp	5-5
4.2.2.2.2	No-Clean Process	4-5	5.1.2	Insulation Clearance if No Support Crimp	5-7
4.3	Solder Connection	4-6	5.1.3	Conductor Crimp	5-7
4.3.1	General Requirements	4-7	5.1.4	Crimp Bellmouth	5-9
4.3.2	Soldering Anomalies	4-8	5.1.5	Conductor Brush	5-10
4.3.2.1	Partially Visible or Hidden Solder Connections	4-8	5.1.6	Carrier Cutoff Tab	5-12
4.4	Wire/Lead Preparation, Tinning	4-9	5.1.7	Individual Wire Seal	5-13
4.5	Wire Insulation	4-11	5.2	Stamped and Formed – Closed Barrel	5-15
4.5.1	Clearance	4-11	5.2.1	Insulation Clearance	5-16
4.5.2	Postsolder Damage	4-13	5.2.2	Insulation Support Crimp	5-17
4.6	Insulation Sleeve	4-14	5.2.3	Conductor Crimp and Bellmouth	5-18
4.7	Soldered Strand Separation (Birdcaging)	4-16	5.2.4	Cutoff Tabs	5-20
4.8	Terminals	4-17	5.3	Machined Contacts	5-21
4.8.1	Turrets and Straight Pins	4-20	5.3.1	Insulation Clearance	5-21
4.8.1.1	Lead/Conductor(s) Placement	4-20	5.3.2	Insulation Support Style	5-23
4.8.1.2	Solder	4-22	5.3.3	Conductor	5-24
4.8.2	Bifurcated	4-23	5.3.4	Crimping	5-26
4.8.2.1	Side Route	4-23	5.3.5	CMA Buildup	5-28
4.8.2.2	Bottom and Top Route	4-25	5.4	Termination Ferrule Crimp	5-30
4.8.2.3	Staked/Constrained Wires	4-26	5.5	Crimped Terminals	5-32
4.8.2.4	Solder	4-27	6.0	INSULATION DISPLACEMENT CONNECTION (IDC)	6-1
4.8.3	Slotted	4-29	6.1	Mass Termination, Flat Cable	6-1
4.8.3.1	Lead/Conductor(s) Placement	4-29	6.1.1	End Cutting	6-1
4.8.3.2	Solder	4-30	6.1.2	Notching	6-2
4.8.4	Pierced/Perforated/Punched	4-31	6.1.3	Planar Ground Plane Removal	6-3
4.8.4.1	Lead/Conductor(s) Placement	4-31	6.1.4	Connector Position	6-4
4.8.4.2	Solder	4-32	6.1.5	Connector Skew and Lateral Position	6-6
4.8.5	Hook	4-33			

Table of Contents (cont.)

6.2 Discrete Wire Termination	6-10	9.2.2 Wire Dress	9-6
6.2.1 General	6-10	9.2.2.1 Straight Approach	9-7
6.2.2 Position of Wire	6-11	9.2.2.2 Side Approach	9-8
6.2.3 Overhang (Extension)	6-12	9.3 Sleeving and Boots	9-9
6.2.4 Insulation Crimp	6-13	9.3.1 Position	9-9
6.2.5 Damage in Connection Area	6-15	9.3.2 Bonding	9-10
6.2.6 End Connectors	6-16	9.4 Connector Damage	9-13
6.2.7 Pass Through Connectors	6-17	9.4.1 Criteria	9-13
6.2.8 Wiremount Connectors	6-18	9.4.2 Limits – Hard Face – Mating Surface	9-14
6.2.9 Subminiature D-Connector (Series Bus Connector)	6-19	9.4.3 Limits – Soft Face – Mating Surface or Rear Seal Area	9-15
6.2.10 Modular Connectors (RJ Type)	6-21	9.4.4 Contacts	9-16
7.0 Ultrasonic Welding	7-1	9.5 Installation of Contacts and Sealing Plugs into Connectors	9-17
7.1 Insulation Clearance	7-1	9.5.1 Installation of Contacts	9-17
7.2 Weld Nugget	7-3	9.5.2 Installation of Sealing Plugs	9-19
8.0 Splices	8-1	10.0 Over-Molding/Potting	10-1
8.1 Soldered Splices	8-1	10.1 Over-Molding	10-2
8.1.1 Mesh	8-2	10.1.1 Mold Fill	10-2
8.1.2 Wrap	8-3	10.1.1.1 Inner	10-2
8.1.3 Hook	8-4	10.1.1.2 Outer	10-5
8.1.4 Lap	8-5	10.1.1.2.1 Mismatch	10-8
8.1.4.1 Two or More Conductors	8-5	10.1.1.2.2 Fit	10-9
8.1.4.2 Insulation Opening (Window)	8-7	10.1.1.2.3 Cracks, Flow Lines, Chill Marks (Knit Lines) or Weld Lines	10-12
8.1.5 Heat Shrinkable Solder Devices	8-8	10.1.1.2.4 Color	10-14
8.2 Crimped Splices	8-10	10.1.2 Blow Through	10-15
8.2.1 Barrel	8-10	10.1.3 Position	10-16
8.2.1.1 Insulation Opening (Window)	8-13	10.1.4 Flashing	10-19
8.2.2 Double Sided	8-14	10.1.5 Wire Insulation, Jacket or Sleeving Damage	10-21
8.2.3 Contact	8-17	10.1.6 Curing	10-22
8.2.4 Wire In-Line Junction Devices (Jiffy Junctions)	8-18	10.2 Potting (Thermoset Molding)	10-23
8.3 Ultrasonic Weld Splices	8-19	10.2.1 Filling	10-23
8.4 Sleeving Over Splices	8-20	10.2.2 Fit to Wire or Cable	10-26
9.0 Connectorization	9-1	10.2.3 Curing	10-28
9.1 Hardware Mounting	9-1	10.3 Over-Molding of Flexible Flat Ribbon	10-29
9.1.1 Jackpost – Height	9-1	10.3.1 Mounting and Alignment Feature Adhesion	10-31
9.1.2 Jackscrews – Protrusion	9-2	10.3.2 Adhesion Between Ribbon and Connector Potting	10-31
9.1.3 Retaining Clips	9-3	10.3.3 Mounting Hardware	10-32
9.1.4 Connector Alignment	9-4	11.0 Measuring Cable Assemblies and Wires	11-1
9.2 Strain Relief	9-5		
9.2.1 Clamp Fit	9-5		

Table of Contents (cont.)

6.1.6	Retention	6-7	9.2.2	Wire Dress	9-7
6.2	Discrete Wire Termination	6-8	9.2.2.1	Straight Approach	9-7
6.2.1	General	6-8	9.2.2.2	Side Approach	9-8
6.2.2	Position of Wire	6-9	9.3	Sleeving and Boots	9-9
6.2.3	Overhang (Extension)	6-9	9.3.1	Position	9-9
6.2.4	Insulation Crimp	6-11	9.3.2	Bonding	9-10
6.2.5	Damage in Connection Area	6-12	9.4	Connector Damage	9-12
6.2.6	End Connectors	6-13	9.4.1	Criteria	9-12
6.2.7	Pass Through Connectors	6-14	9.4.2	Limits – Hard Face – Mating Surface	9-13
6.2.8	Wiremount Connectors	6-15	9.4.3	Limits – Soft Face – Mating Surface or Rear Seal Area	9-14
6.2.9	Subminiature D-Connector (Series Bus Connector)	6-16	9.4.4	Contacts	9-15
6.2.10	Modular Connectors (RJ Type)	6-18	9.4.4.1	Exposed Sockets, Protected Pins	9-16
7.0	ULTRASONIC WELDING	7-1	9.5	Installation of Contacts and Sealing Plugs into Connectors	9-16
7.1	Insulation Clearance	7-1	9.5.1	Installation of Contacts	9-17
7.2	Weld Nugget	7-2	9.5.2	Installation of Sealing Plugs	9-18
8.0	SPLICES	8-1	10.0	OVER-MOLDING/POTTING	10-1
8.1	Soldered Splices	8-1	10.1	Over-Molding	10-1
8.1.1	Mesh	8-2	10.1.1	Mold Fill	10-1
8.1.2	Wrap	8-2	10.1.1.1	Inner	10-1
8.1.3	Hook	8-3	10.1.1.2	Outer	10-4
8.1.4	Lap	8-3	10.1.1.2.1	Mismatch	10-6
8.1.4.1	Two or More Conductors	8-4	10.1.1.2.2	Fit	10-7
8.1.5	Heat Shrinkable Solder Devices	8-6	10.1.1.2.3	Cracks, Flow Lines, Chill Marks (Knit Lines) or Weld Lines	10-9
8.2	Crimped Splices	8-8	10.1.1.2.4	Color	10-11
8.2.1	Barrel	8-8	10.1.2	Blow Through	10-11
8.2.2	Double Sided	8-10	10.1.3	Position	10-12
8.2.3	Contact	8-12	10.1.4	Flashing	10-15
8.2.4	Wire In-Line Junction Devices	8-13	10.1.5	Wire Insulation, Jacket or Sleeving Damage ..	10-17
8.3	Ultrasonic Weld Splices	8-14	10.2	Potting (Thermoset Molding)	10-18
8.4	Sleeving Over Splices	8-14	10.2.1	Filling	10-18
9.0	CONNECTORIZATION	9-1	10.2.2	Fit to Wire or Cable	10-21
9.1	Hardware Mounting	9-1	10.2.3	Curing	10-22
9.1.1	Jackpost – Height	9-1	10.3	Over-Molding of Flexible Flat Ribbon	10-23
9.1.2	Jackscrews – Protrusion	9-2	10.3.1	Mounting and Alignment Feature Adhesion ..	10-25
9.1.3	Retaining Clips	9-3	10.3.2	Adhesion Between Ribbon and Connector Potting	10-25
9.1.4	Connector Alignment	9-4	10.3.3	Mounting Hardware	10-26
9.2	Strain Relief	9-5			
9.2.1	Clamp Fit	9-5			

Table of Contents (cont.)

11.1	Measuring – Cable and Wire Length			
	Tolerance	11-1		
11.2	Measuring – Cable	11-1		
11.2.1	Reference Surfaces –			
	Straight/Axial Connectors	11-1		
11.2.2	Reference Surfaces –			
	Right-Angle Connectors	11-2		
11.2.3	Length	11-2		
11.2.4	Breakout	11-3		
11.2.4.1	Breakout Measurement Points	11-3		
11.2.4.2	Breakout Length	11-4		
11.3	Measuring – Wire	11-5		
11.3.1	Electrical Terminal Reference Location ...	11-5		
11.3.2	Length	11-6		
12.0	Marking/Labeling	12-1		
12.1	Content	12-1		
12.2	Legibility	12-2		
12.3	Permanency	12-3		
12.4	Location and Orientation	12-4		
12.5	Functionality	12-5		
12.6	Marker Sleeve	12-6		
12.6.1	Wrap Around	12-6		
12.6.2	Tubular	12-8		
12.7	Flag Markers	12-9		
12.7.1	Adhesive	12-9		
12.8	Tie Wrap Markers	12-10		
13.0	Coaxial and Biaxial Cable Assemblies	13-1		
13.1	Stripping	13-1		
13.2	Center Conductor Termination	13-4		
13.2.1	Crimp	13-4		
13.2.2	Solder	13-6		
13.3	Solder Ferrule Pins	13-8		
13.3.1	General	13-8		
13.3.2	Insulation	13-10		
13.4	Coaxial Connector –			
	Printed Wire Board Mount	13-11		
13.5	Coaxial Connector – Center Conductor			
	Length – Right Angle Connector	13-12		
13.6	Coaxial Connector –			
	Center Conductor Solder	13-13		
13.7	Coaxial Connector – Terminal Cover	13-15		
13.7.1	Soldering	13-15		
13.7.2	Press Fit	13-16		
13.8	Shield Termination	13-17		
13.8.1	Clamped Ground Rings	13-17		
13.8.2	Crimped Ferrule	13-18		
13.9	Center Pin	13-20		
13.9.1	Position	13-20		
13.9.2	Damage	13-21		
13.10	Semirigid Coax	13-22		
13.10.1	Bending and Deformation	13-23		
13.10.2	Surface Condition	13-25		
13.10.2.1	Solid	13-25		
13.10.2.2	Conformable Cable	13-27		
13.10.3	Dielectric Cutoff	13-28		
13.10.4	Dielectric Cleanliness	13-30		
13.10.5	Center Conductor Pin	13-31		
13.10.5.1	Point	13-32		
13.10.5.2	Damage	13-34		
13.10.6	Semirigid Coax – Solder	13-34		
13.11	Swage-Type Connector	13-36		
13.12	Soldering and Stripping of Biaxial/Multi-Axial			
	Shielded Wire	13-37		
13.12.1	Jacket and Tip Installation	13-37		
13.12.2	Ring Installation	13-39		
14.0	Securing	14-1		
14.1	Tie Wrap/Lacing Application	14-1		
14.1.1	Tightness	14-6		
14.1.2	Damage	14-7		
14.1.3	Spacing	14-7		
14.2	Breakouts	14-8		
14.2.1	Individual Wires	14-8		
14.2.2	Spacing	14-9		
14.3	Routing	14-12		
14.3.1	Wire Crossover	14-12		
14.3.2	Bend Radius	14-13		
14.3.3	Coaxial Cable	14-14		
14.3.4	Unused Wire Termination	14-15		
14.3.4.1	Shrink Sleeving	14-15		
14.3.4.2	Flexible Sleeving	14-16		
14.3.5	Ties over Splices and Ferrules	14-16		
14.4	Broom Stitching	14-17		
15.0	Harness/Cable Electrical Shielding	15-1		

Table of Contents (cont.)

11.0	MEASURING CABLE ASSEMBLIES AND WIRES	11-1	13.7.2	Press Fit	13-13
11.1	Cable and Wire Length Tolerance	11-1	13.8	Shield Termination	13-13
11.2	Cable	11-1	13.8.1	Clamped Ground Rings	13-13
11.2.1	Straight/Axial Connectors	11-1	13.8.2	Crimped Ferrule	13-14
11.2.2	Right-Angle Connectors	11-1	13.9	Center Pin	13-16
11.2.3	Length	11-2	13.9.1	Position	13-16
11.2.4	Breakout	11-2	13.9.2	Damage	13-17
11.2.4.1	Breakout Measurement Points	11-2	13.10	Semirigid Coax	13-17
11.2.4.2	Breakout Length	11-3	13.10.1	Bending and Deformation	13-18
11.3	Wire	11-3	13.10.2	Surface Condition	13-20
11.3.1	Electrical Terminal Reference Location	11-3	13.10.2.1	Solid	13-20
11.3.2	Length	11-4	13.10.2.2	Conformable Cable	13-21
12.0	MARKING/LABELING	12-1	13.10.3	Dielectric Cutoff	13-22
12.1	Content	12-1	13.10.4	Dielectric Cleanliness	13-24
12.2	Legibility	12-2	13.10.5	Center Conductor Pin	13-24
12.3	Permanency	12-3	13.10.5.1	Damage	13-25
12.4	Location and Orientation	12-4	13.10.6	Solder	13-25
12.5	Direct Marking	12-5	13.11	Swage-Type Connector	13-27
12.6	Marker Sleeve	12-6	13.12	Soldering and Stripping of Biaxial/Multi-Axial Shielded Wire	13-28
12.6.1	Wrap Around	12-6	13.12.1	Jacket and Tip Installation	13-28
12.6.2	Tubular	12-7	13.12.2	Ring Installation	13-30
12.7	Flag Markers	12-7	14.0	SECURING	14-1
12.7.1	Adhesive	12-7	14.1	Restraining Device Application	14-1
12.8	Tie Wrap Markers	12-8	14.1.1	Tightness	14-6
13.0	COAXIAL AND BIAxIAL CABLE ASSEMBLIES	13-1	14.1.2	Damage	14-7
13.1	Stripping	13-1	14.1.3	Spacing	14-8
13.2	Center Conductor Termination	13-4	14.2	Breakouts	14-8
13.2.1	Crimp	13-4	14.2.1	Individual Wires	14-8
13.2.2	Solder	13-5	14.2.2	Spacing	14-9
13.3	Solder Ferrule Pins	13-6	14.3	Routing	14-12
13.3.1	General	13-6	14.3.1	Wire Crossover	14-12
13.3.2	Insulation	13-7	14.3.2	Bend Radius	14-13
13.4	Printed Wire Board Mount	13-8	14.3.3	Coaxial Cable	14-14
13.5	Right Angle Connector	13-9	14.3.4	Unused Wire Termination	14-15
13.6	Center Conductor Solder	13-10	14.3.4.1	Shrink Sleeving	14-15
13.7	Terminal Cover	13-12	14.3.4.2	Flexible Sleeving	14-16
13.7.1	Soldering	13-12	14.3.5	Restraining Device over Splices and Ferrules	14-16

Table of Contents (cont.)

15.1 Braided	15-1	17.2.1.1 Minimum Torque	17-5
15.1.1 Direct Applied	15-2	17.2.2 Wires	17-7
15.1.2 Prewoven	15-4	17.2.2.1 Solid Wires	17-8
15.2 Shield Termination	15-5	17.2.2.2 Stranded Wires	17-10
15.2.1 Shield Jumper Wire	15-5	17.2.3 Safety Wiring	17-11
15.2.1.1 Attached Lead	15-5	17.2.4 Safety Cable	17-13
15.2.1.1.1 Solder	15-6	17.3 Wire/Harness Installation	17-14
15.2.1.1.2 Crimp	15-10	17.3.1 Stress Relief	17-14
15.2.1.2 Shield Braid	15-11	17.3.2 Wire Dress	17-15
15.2.1.2.1 Woven	15-11	17.3.3 Service Loops	17-16
15.2.1.2 Combed and Twisted	15-11	17.3.4 Clamping	17-17
15.2.1.3 Daisy Chain	15-12	17.3.5 Tie Wrap/Lacing	17-17
15.2.1.4 Common Ground Point	15-12	17.3.6 Raceways	17-18
15.2.2 Unterminated Shield	15-13	17.3.7 Grommets	17-19
15.2.2.1 Shield Not Folded Back	15-13	17.3.7.1 Sealing Not Required	17-19
15.2.2.2 Shield Folded Back	15-14	17.3.7.2 Sealing Required	17-20
15.3 Shield Termination – Connector	15-15	18.0 Solderless Wrap	18-1
15.3.1 Shrink	15-15	19.0 Testing	19-1
15.3.2 Crimp	15-17	19.1 Nondestructive Tests	19-1
15.3.3 Shield Jumper Wire Attachment	15-19	19.2 Testing After Rework or Repair	19-1
15.3.4 Soldered	15-20	19.3 Intended Table Usage	19-1
15.4 Shield Termination – Splicing Prewoven	15-20	19.4 Electrical Test	19-2
15.4.1 Soldered	15-21	19.4.1 Selection	19-2
15.4.2 Tie/Tape On	15-23	19.5 Electrical Test Methods	19-3
15.5 Tapes – Barrier and Conductive, Adhesive or Non-Adhesive	15-24	19.5.1 Continuity	19-3
15.6 Conduit (Shielding)	15-25	19.5.2 Shorts	19-4
15.7 Shrink Tubing – Conductive Lined	15-26	19.5.3 Dielectric Withstanding Voltage (DWV)	19-5
16.0 Cable/Wire Harness Protective Coverings	16-1	19.5.4 Insulation Resistance (IR)	19-6
16.1 Braid	16-1	19.5.5 Voltage Standing Wave Ratio (VSWR)	19-7
16.1.1 Direct Applied	16-1	19.5.6 Insertion Loss	19-7
16.1.2 Prewoven	16-3	19.5.7 Reflection Coefficient	19-8
16.2 Sleeving/Shrink Tubing	16-5	19.5.8 User Defined	19-8
16.2.1 Sealant	16-6	19.6 Mechanical Test	19-9
16.3 Spiral Plastic Wrap (Spiral Wrap Sleeving)	16-7	19.6.1 Selection	19-9
16.4 Wire Loom Tubing – Split and Unsplit	16-8	19.7 Mechanical Test Methods	19-10
16.5 Tapes, Adhesive and Non-Adhesive	16-8	19.7.1 Crimp Height (Dimensional Analysis)	19-10
17.0 Finished Assembly Installation	17-1	19.7.1.1 Terminal Positioning	19-11
17.1 General	17-1	19.7.2 Pull Force (Tensile)	19-12
17.2 Hardware Installation	17-2	19.7.2.1 Without Documented Process Control	19-13
17.2.1 Threaded Fasteners	17-3	19.7.3 Crimp Force Monitoring	19-17
		19.7.4 Crimp Tool Qualification	19-17
		19.7.5 Contact Retention Verification	19-17

Table of Contents (cont.)

14.4 Broom Stitching	14-17	16.5 Tapes, Adhesive and Non-Adhesive	16-8
15.0 HARNESS/CABLE ELECTRICAL SHIELDING	15-1	17.0 FINISHED ASSEMBLY INSTALLATION	17-1
15.1 Braided	15-1	17.1 General	17-1
15.1.1 Direct Applied	15-2	17.2 Hardware Installation	17-3
15.1.2 Prewoven	15-3	17.2.1 Threaded Fasteners	17-4
15.2 Shield Termination	15-4	17.2.1.1 Minimum Torque	17-6
15.2.1 Shield Jumper Wire	15-4	17.2.2 Wires	17-8
15.2.1.1 Attached Lead	15-4	17.2.2.1 Solid Wires	17-8
15.2.1.1.1 Solder	15-4	17.2.2.2 Stranded Wires	17-10
15.2.1.1.2 Crimp	15-7	17.2.3 Safety Wiring	17-11
15.2.1.2 Shield Braid	15-8	17.2.4 Safety Cable	17-13
15.2.1.2.1 Woven	15-8	17.3 Wire/Harness Installation	17-14
15.2.1.2.2 Combed and Twisted	15-8	17.3.1 Stress Relief	17-14
15.2.1.3 Daisy Chain	15-9	17.3.2 Wire Dress	17-15
15.2.1.4 Common Ground Point	15-10	17.3.3 Service Loops	17-16
15.2.2 Unterminated Shield	15-10	17.3.4 Clamping	17-16
15.2.2.1 Shield Not Folded Back	15-11	17.3.5 Restraining Devices	17-17
15.2.2.2 Shield Folded Back	15-11	17.3.6 Raceways	17-17
15.3 Connector	15-12	17.3.7 Grommets	17-19
15.3.1 Shrink	15-12	17.3.7.1 Sealing Not Required	17-19
15.3.2 Crimp	15-13	17.3.7.2 Sealing Required	17-20
15.3.3 Shield Jumper Wire Attachment	15-15	18.0 SOLDERLESS WRAP	18-1
15.3.4 Soldered	15-16	19.0 TESTING	19-1
15.4 Splicing Prewoven	15-16	19.1 Nondestructive Tests	19-1
15.4.1 Soldered	15-17	19.2 Testing After Rework or Repair	19-1
15.4.2 Tie/Tape On	15-18	19.3 Electrical Test	19-1
15.5 Tapes – Barrier and Conductive, Adhesive or Non-Adhesive	15-19	19.3.1 Electrical Test Methods	19-1
15.6 Conduit (Shielding)	15-20	19.3.1.1 Continuity	19-1
15.7 Shrink Tubing – Conductive Lined	15-20	19.3.1.2 Shorts	19-2
16.0 CABLE/WIRE HARNESS PROTECTIVE COVERINGS	16-1	19.3.1.3 Dielectric Withstanding Voltage (DWV)	19-2
16.1 Braid	16-1	19.3.1.4 Insulation Resistance (IR)	19-3
16.1.1 Direct Applied	16-1	19.3.1.5 Voltage Standing Wave Ratio (VSWR)	19-4
16.1.2 Prewoven	16-3	19.3.1.6 Insertion Loss	19-4
16.2 Sleeving/Shrink Tubing	16-5	19.3.1.7 Reflection Coefficient	19-4
16.2.1 Sealant	16-6	19.4 Mechanical Test	19-5
16.3 Spiral Plastic Wrap (Spiral Wrap Sleeving)	16-7	19.4.1 Mechanical Test Methods	19-5
16.4 Wire Loom Tubing – Split and Unsplit	16-8	19.4.1.1 Crimp Height	19-5
		19.4.1.2 Pull Force (Tensile)	19-6
		19.4.1.3 Contact Retention Verification	19-8

Table of Contents (cont.)

19.7.6	RF Connector Shield Pull Force (Tensile)	19-18
19.7.7	RF Connector Shield Ferrule Torsion	19-19
19.7.8	User Defined	19-19

20.0 High Voltage Applications 20-1

Appendix A Terms and Definitions A-1

Appendix B Reproducible Test Tables B-1

Appendix C Guidelines for Soldering Tools and Equipment C-1

Appendix D X-Ray Guidelines D-1

Tables

Table 1-1	Magnification Aid Applications – Wire and Wire Connections	1-5
Table 1-2	Magnification Aid Applications – Other	1-6
Table 3-1	Allowable Strand Damage	3-3
Table 4-1	Maximum Limits of Solder Bath Contaminant	4-2
Table 4-2	Solder Connection Anomalies	4-10
Table 4-3	Turret or Straight Pin Terminal Lead/Wire Placement	4-22
Table 4-4	Bifurcated Terminal Lead/Wire Placement – Side Route	4-25
Table 4-5	Bifurcated Terminal Lead/Wire Placement – Bottom Route	4-27
Table 4-6	Staking Requirements of Side Route Straight Through Connections – Bifurcated Terminals	4-29
Table 4-7	Pierced/Perforated/Punched Terminal Lead/Wire Placement	4-34
Table 4-8	Hook Terminal Lead/Wire Placement	4-37
Table 4-9	AWG 30 and Smaller Wire Wrap Requirements	4-44
Table 11-1	Cable/Wire Length Measurement Tolerance	11-1
Table 13-1	Coaxial and Biaxial Shield and Center Conductor Damage	13-1
Table 13-2	Semirigid Coax Deformation	13-24
Table 13-3	Dielectric Cutoff	13-28
Table 14-1	Minimum Bend Radius Requirements	14-13
Table 17-1	Minimum Swaged Ferrule Pull-Off Load	17-13
Table 19-1	Electrical Test Requirements	19-3

Table 19-2	Continuity Test Minimum Requirements	19-4
Table 19-3	Shorts Test (low voltage isolation) Minimum Requirements	19-5
Table 19-4	Dielectric Withstanding Voltage Test (DWV) Minimum Requirements	19-6
Table 19-5	Insulation Resistance (IR) Test Minimum Requirements	19-7
Table 19-6	Voltage Standing Wave Ratio (VSWR) Test Parameters	19-8
Table 19-7	Insertion Loss Test Parameters	19-8
Table 19-8	Reflection Coefficient Test Parameters	19-9
Table 19-9	Mechanical Test Requirements	19-10
Table 19-10	Crimp Height Testing	19-11
Table 19-11	Pull Force Testing Minimum Requirements	19-14
Table 19-12	Pull Test Force Values	19-15
Table 19-13	Pull Test Force Values (Classes 1 & 2) For UL, SAE, GM and Volvo	19-16
Table 19-14	Pull Test Force Values (Classes 1 & 2) For IEC	19-17
Table 19-15	RF Connector Shield Pull Force Testing	19-19
Table A-1	Electrical Clearance	A-2
Table 19-1	Electrical Test Requirements	B-2
Table 19-2	Continuity Test Minimum Requirements	B-3
Table 19-3	Shorts Test (low voltage isolation) Minimum Requirements	B-4
Table 19-4	Dielectric Withstanding Voltage Test (DWV) Minimum Requirements	B-5
Table 19-5	Insulation Resistance (IR) Test Minimum Requirements	B-6
Table 19-6	Voltage Standing Wave Ratio (VSWR) Test Parameters	B-7
Table 19-7	Insertion Loss Test Parameters	B-8
Table 19-8	Reflection Coefficient Test Parameters	B-9
Table 19-9	Mechanical Test Requirements	B-10
Table 19-10	Crimp Height Testing	B-11
Table 19-11	Pull Force Testing Minimum Requirements	B-12
Table 19-15	RF Connector Shield Pull Force Testing	B-13

Table of Contents (cont.)

19.4.1.4 RF Connector Shield Pull Force (Tensile) 19-8

19.4.1.5 RF Connector Shield Ferrule Torsion 19-8

20.0 HIGH VOLTAGE APPLICATIONS 20-1

Appendix A Terms and Definitions A-1

Appendix B Reproducible Test Tables B-1

Appendix C Guidelines for Soldering Tools and Equipment C-1

Appendix D X-Ray Guidelines D-1

Tables

Table 1-1 Magnification Aid Applications – Wire and Wire Connections 1-5

Table 1-2 Magnification Aid Applications – Other 1-6

Table 3-1 Allowable Strand Damage 3-2

Table 4-1 Maximum Limits of Solder Bath Contaminant 4-2

Table 4-2 Solder Connection Anomalies 4-8

Table 4-3 Turret or Straight Pin Terminal Lead/Conductor(s) Placement 4-20

Table 4-4 Bifurcated Terminal Lead/Conductor(s) Placement – Side Route 4-23

Table 4-5 Bifurcated Terminal Lead/Conductor(s) Placement – Bottom Route 4-25

Table 4-6 Staking Requirements of Side Route Straight Through Connections – Bifurcated Terminals 4-26

Table 4-7 Pierced/Perforated/Punched Terminal Lead/Conductor(s) Placement 4-31

Table 4-8 Hook Terminal Lead/Conductor(s) Placement 4-33

Table 4-9 AWG 30 and Smaller Wire Wrap Requirements 4-39

Table 11-1 Cable/Wire Length Measurement Tolerance 11-1

Table 13-1 Coaxial and Biaxial Shield and Center Conductor Damage 13-1

Table 13-2 Semirigid Coax Deformation 13-19

Table 13-3 Dielectric Cutoff 13-22

Table 14-1 Minimum Bend Radius Requirements 14-13

Table 15-1 Braid Damage 15-3

Table 17-1 Minimum Swaged Ferrule Pull-Off Load 17-13

Table 19-1 Continuity Test Minimum Requirements 19-1

Table 19-2 Shorts (Low Voltage Isolation) Test Minimum Requirements 19-2

Table 19-3 Dielectric Withstanding Voltage (DWV) Test Minimum Requirements 19-2

Table 19-4 Insulation Resistance (IR) Test Minimum Requirements 19-3

Table 19-5 Voltage Standing Wave Ratio (VSWR) Test Parameters 19-4

Table 19-6 Insertion Loss Test Parameters 19-4

Table 19-7 Reflection Coefficient Test Parameters 19-4

Table 19-8 Pull Test Force Values 19-7

Table 19-9 RF Connector Shield Pull Force Testing 19-8

Table A-1 Electrical Clearance A-2

Table 19-1 Continuity Test Minimum Requirements B-2

Table 19-2 Shorts (Low Voltage Isolation) Test Minimum Requirements B-3

Table 19-3 Dielectric Withstanding Voltage (DWV) Test Minimum Requirements B-4

Table 19-4 Insulation Resistance (IR) Test Minimum Requirements B-5

Table 19-5 Voltage Standing Wave Ratio (VSWR) Test Parameters B-6

Table 19-6 Insertion Loss Test Parameters B-7

Table 19-7 Reflection Coefficient Test Parameters B-8

Table 19-9 RF Connector Shield Pull Force Testing B-9

1.0 General

1.1 Scope This standard prescribes practices and requirements for the manufacture of cable, wire and harness assemblies. This standard does not provide criteria for cross-section or X-ray evaluation. For X-ray guidelines, see Appendix D X-Ray Guidelines.

If a conflict occurs between the English and translated versions of this document, the English version will take precedence.

The illustrations in this document portray specific points noted in the title of each section. The development committee recognizes that different parts of the industry have different definitions for some terms used herein. For the purposes of this document, the terms cable and wire harness are used interchangeably.

IPC/WHMA-A-620 can be used as a standalone document for purchasing products, however it does not specify frequency of in-process inspection or frequency of end product inspection. No limit is placed on the number of process indicators or the number of allowable repair/rework of defects. Such information should be developed with a statistical process control plan (see IPC-9191).

1.2 Purpose This standard describes materials, methods, tests and acceptability criteria for producing crimped, mechanically secured, or soldered interconnections and the related assembly activities associated with cable and harness assemblies.

The intent of this document is to rely on process control methodology to ensure consistent quality levels during the manufacture of products.

Any method that produces an assembly conforming to the acceptability requirements described in this standard may be used.

Standards may be updated at any time, including with the use of amendments. The use of an amendment or newer revision is not automatically required. The revision in effect shall [D1D2D3] be as specified by the User.

1.3 Classification Use of this standard requires agreement on the Class to which the product belongs. The User has the ultimate responsibility for identifying the Class to which the assembly is evaluated. If the User does not establish and document the acceptance Class, the Manufacturer may do so. Criteria defined in this standard reflect three Product Classes, which are as follows:

Class 1 General Electronic Products

Includes products suitable for applications where the major requirement is the function of the completed assembly.

Class 2 Dedicated Service Electronic Products

Includes products where continued performance and extended life is required, and for which uninterrupted service is desired but not critical. Typically, the end-use environment would not cause failures.

Class 3 High Performance/Harsh Environment Electronic Products

Includes products where continued performance or performance-on-demand is critical, equipment downtime cannot be tolerated, end-use environment may be uncommonly harsh, and the equipment must function when required, such as life support systems and other critical systems.

1.4 Measurement Units and Applications This document uses the International System of Units (SI) in accordance with IEEE/ASTM SI 10, American National Standard for Metric Practice (Section 3). Imperial English equivalent units follow in brackets. The derived SI units used in this document are millimeters (mm) [in] for dimensions and dimensional tolerances, Celsius (°C) [°F] for temperature and temperature tolerances, grams (g) [oz] for weight, and lux (lx) [foot-candles] for illuminance.

1.4.1 Verification of Dimensions Where not specifically invoked by this standard, actual measurements, e.g., of specific solder fillet dimensions, determination of damage and wrap percentages, are not required except for referee purposes.

1.5 Definition of Requirements The words "shall" or "shall not" are used in the text of this document wherever there is a requirement for materials, process or acceptance of cable, wire and harness assemblies.

Where the words "shall" or "shall not" indicates a requirement for at least one Class, the requirements for each Class are in brackets next to the "shall" or "shall not" requirement.

N = No requirement has been established for this Class

A = Acceptable

P = Process Indicator

D = Defect

Examples:

[A1P2D3] is Acceptable Class 1, Process Indicator Class 2 and Defect Class 3

[N1D2D3] is Requirement Not Established Class 1, Defect Classes 2 and 3

1.0 GENERAL

1.1 Scope This standard prescribes practices and requirements for the manufacture of cable, wire and harness assemblies. This standard does not provide criteria for cross-section or X-ray evaluation. For X-ray guidelines, see Appendix D X-Ray Guidelines.

If a conflict occurs between the English and translated versions of this document, the English version will take precedence.

The illustrations in this document portray specific points noted in the title of each section. The development committee recognizes that different parts of the industry have different definitions for some terms used herein. For the purposes of this document, the terms cable and wire harness are used interchangeably.

IPC/WHMA-A-620 can be used as a standalone document for purchasing products, however it does not specify frequency of in-process inspection or frequency of end product inspection. No limit is placed on the number of process indicators or the number of allowable repair/rework of defects. Such information should be developed with a statistical process control plan (see IPC-9191).

1.2 Purpose This standard describes materials, methods, tests and acceptability criteria for producing crimped, mechanically secured, or soldered interconnections and the related assembly activities associated with cable and wire harness assemblies.

The intent of this document is to rely on process control methodology to ensure consistent quality levels during the manufacture of products.

It is acceptable to use any method that produces an assembly conforming to the acceptability requirements described in this standard.

Standards may be updated at any time, including with the use of amendments. The use of an amendment or newer revision is not automatically required. The revision in effect shall [D1D2D3] be as specified by the User.

1.3 Classification Use of this standard requires agreement on the Class to which the product belongs. The User has the ultimate responsibility for identifying the Class to which the assembly is evaluated. If the User does not establish and document the acceptance Class, the Manufacturer may do so. Criteria defined in this standard reflect three Product Classes, which are as follows:

Class 1 General Electronic Products

Includes products suitable for applications where the major requirement is the function of the completed assembly.

Class 2 Dedicated Service Electronic Products

Includes products where continued performance and extended life is required, and for which uninterrupted service is desired but not critical. Typically, the end-use environment would not cause failures.

Class 3 High Performance/Harsh Environment Electronic Products

Includes products where continued performance or performance-on-demand is critical, equipment downtime cannot be tolerated, end-use environment may be uncommonly harsh, and the equipment must function when required, such as life support systems and other critical systems.

1.4 Measurement Units and Applications This document uses the International System of Units (SI) in accordance with IEEE/ASTM SI 10, American National Standard for Metric Practice (Section 3). Imperial English equivalent units follow in brackets. The derived SI units used in this document are millimeters (mm) [in] for dimensions and dimensional tolerances, Celsius (°C) [°F] for temperature and temperature tolerances, grams (g) [oz] for weight, and lux (lx) [foot-candles] for illuminance. Conductor sizes are expressed in American Wire Gauge (AWG).

1.4.1 Verification of Dimensions Where not specifically invoked by this standard, actual measurements, e.g., of specific solder fillet dimensions, determination of damage and wrap percentages, are not required except for referee purposes.

1.4.2 Relationship of AWG and Wire Size AWG numbers increase as the conductor diameter decreases. For example, 22 AWG has a conductor with a smaller diameter than 11 AWG. In this standard, when “smaller than” or “larger than” is used in reference to wire size, it is referencing the wire diameter and not the wire gauge.

1.5 Definition of Requirements The words “shall” or “shall not” are used in the text of this document wherever there is a requirement for materials, process or acceptance of cable and wire harness assemblies.

Where the words “shall” or “shall not” indicates a requirement for at least one Class, the requirements for each Class are in brackets next to the “shall” or “shall not” requirement.